

Greenville Overlook Environmental Daily Status Report



Date: 10/16/09

Weather: Rain **Temperature:** 40s° **Winds:** 0-2 mph (West)

Items Completed Today BrightFields was on site from 0730 to 14:30 to monitor trucks transporting contaminated soil offsite and collect soil samples for screening. Perimeter dust monitoring was not performed due to rain.

BrightFields collected soil samples from Men's Tee Hole 1 (Remediation Area A2) and Practice Green 1 (Area B8). Soil samples were analyzed onsite utilizing an X-Ray Fluorescence analyzer. Selected samples were sent to the laboratory for confirmation analysis.

Items Ongoing:

Lewis Environmental will continue blending and BrightFields will continue to monitor remedial activities and collect soil samples for analysis.

Material Management (Soil/Wood/Water): 20 truckloads of soil were transported to an offsite facility.

Personal Protection Equipment Used by Workers:

Used: Safety glasses Hard hat Steel toe boots
 Nitrile gloves Hearing protection Other:

Sampling or Monitoring Completed:

(if yes, please specify the reason.)

Air monitoring on site No Yes, reason: Rain

Soil sampling on site No Yes, reason: screening and confirmatory samples used to assess contaminant concentrations in the soil.

Visitors Briefed on Environmental Conditions: None

Completed By: John Stratton and John Stevens

